

Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.
KD224503 PTC2200 1 PTC EVG31-050 2 FEC MG3062CL2 2 TOSJ PTC2200-1 2 PTC QM30DY-H 2 MITJ EVG31-050 3 FUJI MJ30BD45 3 MOTA	KDT518 (Cont'd) BUX22 3 APX BUX80 3 PHIN D64VP3 3 GESY DE283 3 DGE SVT7530 3 TRWS TIP555 3 TII KDT519 2N6308 1 MOTA MJ50B2D45 1 MOTA EUV31-050 2 FEC MG50G2CL2 2 TOSJ PMD050PLA45 2 GESY PMD050PLA55 2 GESY PTC2400-1 2 PTC QM50DY-H 2 MITJ MJ50BD45 3 MOTA PTC2400 3 PTC	KE3686 (Cont'd) PN3686-18 1 NSC 2N3821 3 IFC MOTA 2N4340 3 SIX BFW13 3 PHIN DE312 3 DGE THJ4339 3 SPR THJ201 3 SPR TMPF4339 3 SPR TMPFJ201 3 SPR TP4339 3 SPR KE3687 2N3687 1 INL SIX 2N4338 1 SIX 2N5457 1 MOTA PN3687-18 1 NSC 2N3460 3 IFC 2N4341 3 SIX 2N5953 3 IFC BF245A 3 PHIN BFW13 3 PHIN DE312 3 DGE DE451 3 DGE THJ4338 3 SPR THJ5457 3 SPR TMPF4338 3 SPR TMPF5457 3 SPR TP4338 3 SPR	KE4092 2N5639 1 MOTA ITE4092 1 INL PN4092-18 1 NSC PN392-18 1 SIX TIS74 1 IFC BSV79 3 PHIN ITE4392 3 INL MPF4092 3 MOTA SD1107BD 3 TOP THJ5639 3 SPR TMPF5639 3 SPR KE4093 2N5640 1 MOTA ITE4093 1 INL PN4093-18 1 NSC PN393-18 1 SIX TIS75 1 IFC BSV80 3 PHIN ITE4393 3 INL MPF4093 3 MOTA THJ5640 3 SPR TMPF5640 3 SPR KE4220 2N5457 1 INL MOTA A5T3821 1 IFC PN4220-18 1 NSC 2N3821 3 NSC SIX 2N5484 3 INL 2N5953 3 IFC BFW245A 3 PHIN DE451 3 DGE J305 3 SIX THJ5457 3 SPR TMPF5457 3 SPR KE4221 2N5457 1 SIX 2N5458 1 MOTA 2N5459 1 INL A5T3822 1 IFC PN4221-18 1 NSC 2N3822 3 NSC SIX 2N5484 3 INL 2N5951 3 IFC 2N5952 3 IFC 2N5953 3 IFC BFW245A 3 PHIN BF245C 3 PHIN DE451 3 DGE J305 3 SIX THJ5457 3 SPR THJ5458 3 SPR TMPF5457 3 SPR TMPF5458 3 SPR TMPF5459 3 SPR	KE4224 (Cont'd) THJ5949 3 SPR TIS59 3 TII TMPF5949 3 SPR TP5949 3 SPR KE4391 ITE4391 1 INL MPF4391 1 MOTA PN4391-18 1 NSC SIX TIS73 1 IFC 2N5638 3 MOTA PN4391 3 NSC SIX SD1117BD 3 TOP KE4392 ITE4392 1 INL MPF4292 1 MOTA PN4392-18 1 NSC SIX TIS74 1 IFC 2N5639 3 MOTA MPF4392 3 MOTA SD1107BD 3 TOP KE4393 ITE4393 1 INL MPF4393 1 MOTA PN4393-18 1 NSC SIX TIS75 1 IFC 2N5640 3 MOTA PN4393 3 SIX SD1117BD 3 TOP KE4416 2N5245 1 IFC 2N5486 1 MOTA ITE4416 1 INL PN4416 1 SIX PN4416-18 1 NSC 2N4416 3 MOTA 2N5245-18 3 SIX 2N5247 3 IFC 2N5248-18 3 NSC DE129 3 DGE THJ5245 3 SPR THJ5486 3 SPR TMPF5245 3 SPR TMPF5486 3 SPR TP5245 3 SPR KE4856 ITE4391 1 INL MPF4391 1 MOTA PN4391-18 1 SIX PN4856-18 1 NSC TIS73 1 IFC 2N5638 3 MOTA PN4391 3 NSC PN4391-18 3 NSC SD1117BD 3 TOP KE4857 ITE4392 1 INL MPF4392 1 MOTA PN4392-18 1 SIX PN4857-18 1 NSC TIS74 1 IFC 2N5639 3 MOTA PN4392 3 SIX PN4392-18 3 NSC SD1107BD 3 TOP KE4858 ITE4393 1 INL MPF4393 1 MOTA PN4393-18 1 SIX PN4858-18 1 NSC TIS75 1 IFC 2N5640 3 MOTA PN4393 3 SIX PN4393-18 3 NSC KE4859 2N4859 1 MOTA ITE4391 1 INL PN4391-18 1 SIX PN4859-18 1 NSC TIS73 1 IFC 2N5638 3 MOTA DE486 3 DGE MPF4391 3 MOTA PN4391-18 3 NSC SD1117BD 3 TOP THJ4859 3 SPR TMPF4859 3 SPR TP4859 3 SPR KE4860 2N4860 1 MOTA ITE4392 1 INL PN4392-18 1 SIX PN4860-18 1 NSC TIS74 1 IFC 2N5639 3 MOTA DE486 3 DGE MPF4392 3 MOTA PN4392-18 3 NSC SD1107BD 3 TOP THJ4860 3 SPR	KE4860 (Cont'd) TMPF4860 3 SPR TP4860 3 SPR KE4861 2N4861 1 MOTA ITE4393 1 INL PN4393-18 1 SIX PN4861-18 1 NSC TIS75 1 IFC 2N5640 3 MOTA DE486 3 DGE MPF4393 3 MOTA PN4393-18 3 NSC THJ4861 3 SPR TMPF4861 3 SPR TP4861 3 SPR KE5103 2N3823 1 MOTA 2N5952 1 IFC J204 1 INL J305 1 SIX J305-18 1 NSC 2N5484 1 INL 2N5640 3 MOTA 2N5952-18 3 NSC SIX DE459 3 DGE THJ3823 3 SPR THJ5952 3 SPR THJ305 3 SPR TIS58 3 TII TMPF3823 3 SPR TMPF5952 3 SPR TMPFJ305 3 SPR TP3823 3 SPR TP5952 3 SPR KE5104 2N3823 1 MOTA 2N5953 1 IFC ITE4416 1 INL J304 1 SIX J305-18 1 NSC 2N4416 3 MOTA 2N5245 3 IFC 2N5484 3 INL 2N5486 3 INL 2N5640 3 MOTA 2N5952-18 3 SIX 2N5953-18 3 NSC SIX DE459 3 DGE J305 3 SIX PN4416 3 SIX PN4416-18 3 NSC SX3819 3 TII THJ3823 3 SPR THJ5953 3 SPR THJ304 3 SPR TIS58 3 TII TMPF3823 3 SPR TMPF5953 3 SPR TMPFJ304 3 SPR TP3823 3 SPR TP5953 3 SPR KE5105 2N3823 1 MOTA 2N5245 1 IFC ITE4416 1 INL J304-18 1 NSC J306 1 SIX 2N4416 3 MOTA 2N5245-18 3 SIX 2N5248-18 3 NSC DE129 3 DGE DE459 3 DGE PN4416 3 SIX PN4416-18 3 NSC THJ3823 3 SPR THJ5245 3 SPR TMPF3823 3 SPR TMPF5245 3 SPR TP3823 3 SPR TP5245 3 SPR KE5460 2N5460 1 MOTA DE326 3 DGE MPF454 3 MOTA THJ5460 3 SPR TMPF5460 3 SPR KH5196 2N5196 1 INL MP844 3 MPS THJ5196 3 SPR KH5197 2N5197 1 INL 2N5545 3 IFC MP844 3 MPS THJ5197 3 SPR KH5198 2N5198 1 INL 2N5546 3 IFC MP5911 3 MPS THJ5198 3 SPR